

EAST - [Untitled1:1]

File View Edit Tools Window Help

Drafts

Pending

Active

Failed

Saved

Favorites

Tagged (0)

UDC

Queue

Trash

Sort

DB: USPAT - EPO - DERWENT

Default operator: OR

☒ Highlight all hit terms initially

6555005
 5141031
 5484528
 3730959
 4540490
 5910250
 3704223

BBS form

ISM form

Image

Text

HTML

	U	I	Document ID	Issue Date	Pages	Title	Current OR	Current XRef.*
1	<input type="checkbox"/>	<input type="checkbox"/>	US 6555005 B1	20030429	26	Scouring method	210/636	210/321.69; 210/321.89;
2	<input type="checkbox"/>	<input type="checkbox"/>	US 5910250 A	19990608	12	Baffle for conversion of fine bubbles to coarse while filtering with a vertical	210/636	210/220; 210/321.69;
3	<input type="checkbox"/>	<input type="checkbox"/>	US 5484528 A	19960116	17	Filtration equipment for hollow fiber module	210/321.8	210/232; 210/321.79;
4	<input type="checkbox"/>	<input type="checkbox"/>	US 5141031 A	19920825	13	Woven hollow fiber double weft tape with knitted selvedge	139/383R	139/420A; 139/431;
5	<input type="checkbox"/>	<input type="checkbox"/>	US 4540490 A	19850910	10	Apparatus for filtration of a suspension	210/323.2	210/321.69; 210/321.9;
6	<input type="checkbox"/>	<input type="checkbox"/>	US 3730959 A	19730501	6	FABRICATION OF HIGH PRESSURE SEALS FOR WATER	264/263	210/321.9; 210/500.23;
7	<input type="checkbox"/>	<input type="checkbox"/>	US 3704223 A	19721128	24	TEXT AVAILABLE IN USOCR DATABASE	204/601	204/640; 204/665;
8	<input type="checkbox"/>	<input type="checkbox"/>	DE 3730959 A1	19890323	10	Subtraction circuit in 51111 code		
9	<input type="checkbox"/>	<input type="checkbox"/>	US 5910250 A	19990608	12	Baffle for conversion of fine bubbles to coarse bubbles for aqueous media		
10	<input checked="" type="checkbox"/>	<input type="checkbox"/>	WO 9828066 A	19980702	26	Fouling material removal from hollow fibre membranes - with gas bubbles		
11	<input type="checkbox"/>	<input type="checkbox"/>	JP 07080255 A	19950328	17	Filtering device - with hollow yarn modules vertically arranged in separat		

Start

Document6 - Mic

Microsoft Office

eDAN Version 1

EAST - [Unfitt...